Inbound Shipments

(1)

Field Activity
Shipment on
DD Form 1348
(SHP, Doc ID)

DLA shipments: No DSS transactions for shipment/receipt of assets between blocks (1), (2), (3), and (4).

(3)

Orange Park Warehouse
(off base)
DoDAAC: N39824
Inventory/Storage
Maintained in
Desktop computer
Excel Spreadsheets

(2)

A/F - ALC DLA
Shipment on
DD Form 1348
(A2, A5 Doc ID)

DLA NAS JAX
Bldg 110, Door 16
(no DSS acceptance/receipt transactions)

NADEP transport's asset's

NADEP transport's asset's

(4)

NADEP JAX Warehouse
DoDAAC:
N65886, N39825
Inventory/Storage
maintained on
desktop computer
excel
spreadsheets

Depot Repair Cycle

Orange Park Warehouse (off base)

NADEP Jax

Warehouse

(5)

Planner/Scheduler prepare RFI shipping document (DD Form ll49's) & sends items to NAS FISC & notify customer of units completed for appropriate delivery point.

FISC
Preserves/Packs items for DDJF shipment

DLA
Ships items on ZWT Doc ID

(4)
PC notifies Planner/Scheduler of RFI items makes a WCS 275 Transaction selling a unit and H-4 transaction for condemn.

(1)
Planner/Scheduler calls for items for induction from ware-house & uses WCS for Depot induction of items/processing documents & notifies production control

(2)
Production Controller (PC) inducts items into shop

(3)
Shop Repair/Make item RFI

Out Bound Shipments

Planner/Scheduler

send RFI items to FISC

DLA

DDJF Ships items on DSS ZWT transactions only.
DDJF has an
in-box for NADEP to pick-up
copy (1) of DD1149. This procedure verifies asset shipment.

Field Activity
base / location
No DSS acceptance transactions.

Fleet Industrial Supply Center (FISC)
Preserves/Packs items for DDJF shipment. Forwards signed copy (2) of DD1149 back to NADEP.

A/F ALC DLA
location
D6 Doc ID DSS acceptance transaction.